ELLOFAX 11	A	pproved For Release 2001/04/1	3: CIA PDF 82 0045 4007100170010-8 OCD
	e. c. weeder todd: 1 ≈4.00 °	CLASSIFICATION S	ET S
COUNTRY	Ge		REPORT NO.
TOPIC_CO	tibu	is diffield	25X1A
le capper des caledon de la Cappe de la Ca	n The constant of a	Bandon Commiss, and USA & Connection 1 was a. N. of 2000000 of the Confedence of the Confedence of the Connection of the	TO THE PROPERTY OF THE PROPERT
g: ~			TAINED 25X1A
			25X1A
			DATE PREPARED 8 February 1951
			Autolinology (an unaquistated (place or attended under a territoria mentre control con
PAGES	erana romana roma	2 ENCLOSURES (No. & T	PPE) was also assume the companion of th
REMARKS	and the state of t	ngagadiku, ki ondok dalah dalah kanan na anan na anan kanan kanan kanan kanan kanan kanan kanan kanan kanan ka	
regge reproductive give go their galor require	naugh y sweet court	oversomer span, at the level of the . And also in the control of t	
Tag (I.a. pino) - Bullerinka gi, PO 2007 - Ballicha	E140(10##################################	THE PROPERTY AND ASSESSMENT OF THE PROPERTY OF	OFV4V
			25X1X
25X1X	10	by 28 aircraft. Thirteen take-off point, and one g four planes were parked i timual flying, but the nutormined. All hangars but flying had single cockpit alightly more than the no The plane with two cockpi what thinner, and the two	ottbus (N 52/A 57) airfield was occupied twin-engine planes were parked at the roup of three planes and three groups of a front of the hangars. (1) There was consider of planes in the air could not be described. The aircraft used for so The nose of this type plane is pointed se of the double-cockpit planes. (2) ts, however, generally appears to be some-angines project beyond the upper edges of fitted in front of the cockpit, has anrudder assemblies.
	2.	lasted about 10 minutes. After landing, the aircremear the runway. A radio antenna stood at the take which was placed on the g	g all day in a cloudless sky. The flights The planes were refueled from tank trucks. It taxied to the take-off point on the grass truck with an extended directional loop off point. Another radio with a whip antenna round near the take-off point was surrounded radar set was not creeted, only its mast was
	<u> </u>	take-offs and landings were of the landing field was	rictly guarded during flying and blocked when re made. The field path on the western edge graded and blocked from point 65.6 on the 7) road as far north as point 64.5.
	L.	point and observed the approximander's scopes. These	
	5.		ers which arrived recently were seen in the fuel They were not put underground. (5)
To H	•	CLASSIFICATION SI	Document No. No Change in Class. Declassified Glass. Changed To: TS S C
			IMAGE IMPONOUM TAL TO DATE

SECRET,

2



25X1X

- 6. Between 10:30 and 11:30 a.m. on 16 January, 23 twin-engine, low-wing monoplanes with in-line engines and double rudder 25X1A assemblies were seen in front of the hangars. The observation was made from the southern edge of the field. (1) Ho aircraft were seen in the one open hangar. Three of the parked aircraft which were not covered with tarpaulins were surrounded by approximately 20 men who were probably being instructed. The engines of the planes were started individually.
- 7. The building material previously seen on the southern edge of the landing field was shipped away. Only three small temporary buildings were loft. The runway was completed. The area where the building material was previously stored was being graded by about 40 to 50 men using a power shovel.
- 8. There was no flying on 16 January because of occasional showers and a cloud base of 800 meters. No night lighting facilities were on the new runway.

 Were seen.

25X1C

25X1A

Comments.

(1) The number of aircraft indicates that the occupation of the airfield has not changed compared with the last report of 3 January 1951.

25X1A See From the number of planes parked on the landing field it cannot be determined whether one or two bomber regiments are stationed there. According to another source, two bomber regiments are believed to be stationed in Cottbus. Therefore, more aircraft are believed to be parked in the hangars.

- (2) These two aircraft types have been observed at all airfields in the Soviet Zone of Germany which are occupied by bomber regiments. The employment of the two types, probably two versions of the FE-2, is not known.
- (3) The radar set was removed on 16 December 1950, and to date has not been re-erected.

(4)

25X1C

(5) The arrival of new containers is reported for the first time. It is not known whether these are additional containers or replacements for old ones.



